Fly Elite

Service Order 7246: Pinckney Michael M Dba - Completed -

Opened: 06/03/16 04:14P Completed: 06/03/16 04:27P

General Information

Registration No.:	**N28037**	Airframe Serial No.:	79-30949
Make and Model:	BELLANCA 17-30A	FAA Type:	
Tachometer 1 - Current:	1843.82	Tachometer 1 - Total:	1843.82
Total Time Airframe:	1843.82		

Service Description: Replace all bushings on both MLG. Replace all gear taxi springs. Overhaul hydraulic power pak. R&R L front drag strut bracket and R I/B aft trunion bracket. Rig MLG. Perform MLG alignment. R&R one NLG door actuator hydraulic hose.

Discrepancy Summary

#	Approval	Partial Description	Labor Est / Quote	Parts Estimate
		Shop Labor		
1	Approved	Replace all bushings on both MLG. Replace all gear taxi spr	2337.50 E	1084.15
2	Approved	Shop Labor - Shop Asst. Labor	127.50 E	0.00
		Total Estimate: $ 3549.15	2465.00	1084.15

Discrepancy #1 Detail

Shop Labor

Description: Replace all bushings on both MLG. Replace all gear taxi springs. Overhaul hydraulic power pak. R&R L front drag strut bracket and R I/B aft trunion bracket. Rig MLG. Perform MLG alignment. R&R one NLG door actuator hydraulic hose.

Status: Customer Approval: Approved Work: Completed Inspection: Completed

Actions Taken:

Labor Detail: [27.50] Amanda -

Total labor hours: 27.50

Parts Detail: (1) Hydraulic Power PaK – 1000.00
(1) Hydraulic Hose – 84.15

Total parts cost: $ 1084.15

Discrepancy #2 Detail

Description: Shop Labor - Shop Asst. Labor

Status: Customer Approval: Approved Work: Completed Inspection: Completed

Actions Taken:

Labor Detail: [3.00] Amanda -

Total labor hours: 3.00

Parts Detail: Total parts cost: $ 0.00