

Fly Elite

Service Order 7246: Pinckney Michael M DBA

- Completed -

Log Book Entries

Airframe Log (S/N 79-30949)

Replace all bushings on both MLG. Replace all gear taxi springs. Overhaul hydraulic power pak. R&R L front drag strut bracket and R I/B aft trunion bracket. Rig MLG. Perform MLG alignment. R&R one NLG door actuator hydraulic hose.